



## 5510 Part list




|   |       |   |       |   |        |
|---|-------|---|-------|---|--------|
|   |       |   |       |   |        |
| A | 4 PCS | B | 4 PCS | C | 4 PCS  |
|   |       |   |       |   |        |
| D | 4 PCS | E | 1 PCS | F | 16 PCS |
|   |       |   |       |   |        |
| G | 1 PCS | H | 1 PCS | I | 12 PCS |
|   |       |   |       |   |        |
| J | 1 PCS | K | 4PCS  | L | 1 PCS  |


## STEP 1




STEP 2



STEP 3



STEP 4



STEP 5

